

BUILDING SAFETY CERTIFICATE

No. VBK COE/CIVIL/2026-27/101

Dated: 29/7/2026

It is certified that the existing building NUTAN ENGLISH SCHOOL, MALKAPUR (name of the building or premises) at BULDHANA ROAD, MALKAPUR, DIST. BULDHANA – 443101 (address) is having block(s)/Floor(s) as per details below.

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	GROUND	FIRST	SECOND	THIRD		

The building is owned/occupied by LOK SEWA SHIKSHAN BAHUUDDESHIYA MANDAL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of DEPT. OF CIVIL ENGINEERING. (Name of Department/Govt.) on 29/7/2026 (date of inspection) in the presence of DR. A. A. MALOKAR, VBK OF ENGINEERING (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 29/7/2026 for a period of 5 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Component parts of building satisfied the strength of building.
2. Building is well finished.
3. We have taken only non-destructive test.
4. Building premises would fit for human in future.

Issued on 29/7/2026 at MALKAPUR by Pad. Dr. V.B. Kolte College of Engg, Malkapur

*Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail

Signature with Seal

Name

Designation

Name & Address of Department/Office

DR. VBKCOE, Malkapur



Dr. A. A. Malokar
Asst- Professor
Civil Engineering Dep.
DR. VBKCOE, Malkapur

Sandeep
Principal,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.

Pachpande
Manager,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.



Government of Maharashtra Approved
Lok Sewa Shikshan Bahuuddeshiya Mandal's

Padmashri Dr. V. B. Kolte College of Engineering, Malkapur

Recognized By ● AICTE, New Delhi (1-4781081) ● DTE, Mumbai (1182) ● Section 2(f) of UGC
Afiliated To ● SGBAU, Amravati (383) ● MSBTE, Mumbai (1565)
Certified By ● ISO 9001:2015

Tel : (07267) 226700, 295037, Mob. 07267226700 (WhatsApp). Website : www.coemalkapur.ac.in, Email : coemalkapur@rediffmail.com
Address : Muktainagar Road, Malkapur - 443101, Dist - Buldhana (Maharashtra)

● NBA Accredited Diploma & Undergraduate Programs ● NAAC Accredited by B+ Grade ●
OUTWARD: VBKCOE/CIVIL/2026-27/101 Date: 29/07/2026

FORM 'A'

[See Rule 3(1)]

BUILDING SAFETY CERTIFICATE

To,
Principal
Nutan English School,
Malkapur Dist: Buldhana

Sub. : Structural examination under Section 193-A of the Maharashtra Municipal Councils, Nagar Panchayats and Industrial Townships Act 1965 in respect of School **Building of Nutan English School, Malkapur** situated at **Malkapur Dist: Buldhana**.

Address: Buldhana Road, Malkapur Dist: Buldhana
Ref. : Letter No.45 Dated: 22/07/2026

Date of Inspection: 27/07/2026

I/We, the undersigned are Structural Engineers working in area of the Municipal Council of for structural examination purpose.

I/We have been appointed as Structural Engineers by the Municipal Council Malkapur the owner/occupant of the aforesaid building site situated at Malkapur on the land bearing at Malkapur to carry out the structural examination of the building as provided under Section 193-A of the Maharashtra Municipal Councils, Nagar Panchayats and Industrial Townships Act, 1965.

I/We have carried out the structural examination of the aforesaid Nutan English School, building as per the procedure elaborated in the accompanying inspection Report. I/We do hereby certify that I/We have personally visited and checked all the structural components of the building.

On the basis of the examination and verification of the school buildings and as required under provisions of Section 193-A of the Maharashtra Municipal Councils, Nagar Panchayats and Industrial Townships Act, 1965, I/We submit the following certificate:—
"We certify that the school building is good in condition & strength. After testing we seen that all the components parts of building is satisfied in strength. The Building is well finished. The building/premises would fit for human habitation in future.

Date: 29/07/2026



Structural Engineer

Dr. A. A. Malokar

Principal,

Nutan English School, Malkapur,
Ta. Malkapur, Dist. Buldhana.

HOD

Department of Civil Engineering
Pad. Dr. V. B. Kolte College of Engineering
MALKAPUR, Dist. Buldhana (M.S.)

Manager,
Nutan English School, Malkapur,
Ta. Malkapur, Dist. Buldhana.

Principal
Pdm. Dr. V. B. Kolte College of
Engineering, MALKAPUR
Dist. Buldhana (M.S.)



Government of Maharashtra Approved
Lok Sewa Shikshan Bahuuddeshiya Mandal's

Padmashri Dr. V. B. Kolte College of Engineering, Malkapur

Recognized By ● AICTE, New Delhi (1-4781081) ● DTE, Mumbai (1182) ● Section 2(f) of UGC
Affiliated To ● SGBAU, Amravati (383) ● MSBTE, Mumbai (1565)
Certified By ● ISO 9001:2015

Tel : (07267) 226700, 295037, Mob. 07267226700 (WhatsApp). Website : www.coemalkapur.ac.in, Email : coemalkapur@rediffmail.com

Address : Muktainagar Road, Malkapur - 443101, Dist - Buldhana (Maharashtra)

● NBA Accredited Diploma & Undergraduate Programs ● NAAC Accredited by B+ Grade ●
OURWARD: VBKCOE/CIVIL/ST.AUDIT/2026-27/101 **Date: 29/07/2026**

FORM 'B'

[See Rule 3(1)]

STRUCTURAL AUDIT REPORT

(Existing School Building)

Pursuant to the appointment of the undersigned for carrying out the structural examination under Section 193-A of the Maharashtra Municipal councils, Nagar Panchayats and Industrial Townships Act, 1965 the undersigned has inspected School Building of **Nutan English School, Malkapur Dist: Buldhana** situated at Malkapur and has recorded his findings as follows:—

1. The type/class of occupancy in the said building or premises is as under:—

(i) Residential—	NO
(a) High Rise above 1 storey's:	NO
(b) upto 1 storeys	NO
(ii) Commercial:	NO
(iii) Industrial:	NO
(iv) Educational:	YES
(v) Assembly:	NO
(vi) Government:	NO
(vii) Others	NO
2. General/particular condition of the building/premises: GL+3 floor only
3. Particulars of the building/premises:—

i).Number of storey's and basement, if any.	New Building work
ii).Number of exits/staircases/lifts.	Multi Story Building
iii).Details of ceiling/columns/beams/flooring/balconies.	03
iv) Plumbing/Drainage.	YES
v) Parking. (Open space)	YES
4. Location of the building/premises (append the relevant sketch) Plan given.
5. History of recent repairs to the buildings carried out by the owner/ occupier: -

i)Whether complete repairs were done?	YES
ii) Whether structural repairs were done?	YES
iii) Short description of Structural repairs done:	New construction
iv) Whether only terrace water proofing was done?	Good Condition
v) In which year external painting to the building was done.	2025
(vi) Whether plumbing system was repaired?	YES

Sandeep
Principal,
Nutan English School, Malkapur
Ta. Malkapur, Dist. Buldhana.



Dr. D.
Department of Civil Engineering
Pad. Dr. V. B. Kolte College of Engineering
MALKAPUR, Dist. Buldhana. (M. S.)

Pachpande
Manager,
Nutan English School, Malkapur
Ta. Malkapur, Dist. Buldhana.

First Floor:**A) Class Room 01:**

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

B) Class Room 02:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

C) Class Room 03:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
28	16.40	35	19.40

D) Pouch 04

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
28	16.40	35	19.40

E) Class Room: 05

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

F) Class Room: 06

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

Second Floor:**A) Class Room 01:**

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40



Manager,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.

Principal,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.

B) Class Room 02:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

C) Class Room 03:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

D) Library 04

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

E) Class Room: 05

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

F) Class Room: 06

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

Third Floor:

A) Class Room 01:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

B) Class Room 02:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40



Signature
Manager,
 Nutan English School, Malkapur.
 Ta. Malkapur, Dist. Buldhana.

Signature
Principal,
 Nutan English School, Malkapur.
 Ta. Malkapur, Dist. Buldhana.

C) Class Room 03:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

D) Wash Room 04

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

E) Class Room: 05

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

F) Class Room: 06

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

Terrace Floor:


A) Overhead Water Tank 01:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
35	19.40	35	19.40

B) Parapet Wall 02:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
32	18.20	35	19.40

P. Chandra
Manager,
 Nutan English School, Malkapur.
 Ta. Malkapur, Dist. Buldhana.



Dr. V.B. Kolte
 H. O. D.
 Department of Civil Engineering
 Pad. Dr. V.B. Kolte College of Engineering
 MALKAPUR, Dist. Buldhana, (M.S.)

Sandeep
Principal,
 Nutan English School, Malkapur.
 Ta. Malkapur, Dist. Buldhana.

6.As required, detailed survey was carried out along with the following non-destructive/Laboratory tests for the building/premises:-

Non Destructive Test:

Ground Floor:

A) Class Room 01:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

B) Class Room 02:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

C) Class Room 03:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

D) Pricipal Office 04

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

E) Pourch 05:

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40

F) Class Room: 06

Brick Wall	Strength (MPa)	Column	Strength (MPa)
32	18.20	32	18.20
32	18.20	32	18.20
30	17.40	35	19.40



[Signature]
H. O. D.

Department of Civil Engineering
Pad. Dr. V.B. Kolte College of Engineering
MALKAPUR, Dist. Buldhana. (M.S.)

[Signature]
Manager,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.

[Signature]
Principal,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.

7. The observations are as below:-

7.1. Building (External Components)

- A) Whether structure is RCC or load bearing: RCC Structure
- B) Conditions of—Plaster of wall well condition
 - (i) Wall: Wall strength in testing area average: 17.40 MPa
 - (ii) Roof Slab (Ground Floor): Good in strength
 - (iii) Roof Slab (First Floor): Good in strength
 - (iv) R.C.C. Chajjas: Good in strength
 - (v) R.C.C. Porch: NA
 - (vi) R.C.C. Lintels: Good in strength
 - (vii) Settlement: NO
- C) Basement, — Good condition
Condition of Raft and R.C.C. Pardi- NA
- (D) Condition of other Building components: -
 - (i) External Masonry: Good in condition
 - (ii) External Plaster: Good in condition
 - (iii) External paint: YES
 - (iv) Plumbing and Drainage (Vertical): YES Good condition
 - (v) Drainage Chamber/lines: YES
 - (vi) Ducts: Good
- (E) Staircase and lift area: - NA
- (F) Terrace Area :—
 - (i) Condition of RCC Over Head Water Tank : Good condition
 - (ii) Condition of RCC of Lift machine Room: Not Applicable
 - (iii) Condition of masonry and plaster of lift machine room : Not Applicable
 - (iv) Condition of plaster of OHWT: Good in condition
 - (v) Whether leakages noticed through OHWT: NO
 - (vi) Observations on staircase cabin from inside: Good in condition
 - (vii) Observation on parapet masonry, its Plaster and leakages: NA
 - (viii) Observation about leakages at the junction of masonry and terraco
Slab top: Leakages is not observed
 - (ix) Condition of water proofing of terrace: Good condition
 - (x) Condition of spouts: NO
- (G) Ancillary structures:
 - (i) Underground water Tank: Good
 - (ii) Pump Room: Good
 - (iii) Paving: Good condition
 - (iv) Compound wall: Good condition
 - (v) Electrical meter room: Good condition
 - (vi) Society's office: Good condition

8. Other observations :

- (i) Leakage/dampness noticed through walls/Slabs at terrace: Good condition
- (ii) Condition of masonry: Well in condition
- (iii) Condition of internal plaster: Well condition
- (iv) Condition of paint: Well condition
- (v) Condition of toilets in respect of leakages from the upper floor: Good in condition
- (vi) Condition of flooring in rooms and toilets: Good in condition



Sandeep
Manager,
Nutan English School, Malkapur.

Sandeep
Principal,
Nutan English School, Malkapur,
Tal. Malkapur, Dist. Buldhana.

- (vii) Whether any false ceiling is provided in any room which obstructed inspection of ceiling of that room: NO
- (viii) Observations of the complaints(s) made by school/hospital/flat/apartment owner vide separate letter(s) or during inspection of this flat/apartment: NO
- (ix) Lift Wall R.C.C. or Column-Beam Structure: Good in condition
- (x) Other specific observations which are not covered above:

In every year check the stability of building from structural engineers.


9. The Structural examination carried out reveals that—

- (A) We certify that the the Nutan English School building is very good in strength so that building is structurally safe.
- (B) School building premises would fit for human habitation in future.


Place: Malkapur
Date: 29/07/2026



Structural Engineer
Dr. A. A. Malakar


H. O. D.
Department of Civil Engineering
Pad. Dr. V. B. Kolte College of Engineering
MALKAPUR, Dist. Buldhana. (M.S.)


Principal
Pdm. Dr. V. B. Kolte College of
Engineering, MALKAPUR,
Dist. Buldhana. (M.S.)




Manager,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.


Principal,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.

Non Destructive Test



Structural Audit: Nutan English School, Malkapur Dist: Buldhana



Structural Audit: Nutan English School, Malkapur Dist: Buldhana

Pachpande
Manager,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.



Sandeep
Principal,
Nutan English School, Malkapur.
Ta. Malkapur, Dist. Buldhana.